

INDEX

Engineering Design with SolidWorks provides this index to be utilized to revisit information. Do not skip steps in this tutorial-based project book. Our goal is to show how multiple design situations and steps are combined to produce a successful project. Use SolidWorks On-line help and glossary for additional options and commands.

3DContentCentral 2-62

3MMCAPSCREW 2-56

3Point Arc 4-49

4MMCAPSCREW 2-35 – 2-40

80/20 Inc. 1-103, 6-117

A

Add feature to drawing 3-54

Add Relations 1-77, 1-100, 4-39

Air Reservoir Support Assembly 4-81

Alden Products 1-108

Aligned dimension 4-26

Angle Bracket 4-84, 6-103

Angular dimension 1-84, 4-26

Animate Explode 2-50

Animation 2-99

Animation Controller 2-50

Annotation toolbar 3-8

Annotations 3-81

Annotations folder 6-33

Annotations font 3-11

ANSI 1-23

Applied Features 1-99

Arrow Height 3-11

ASME Y14.5 4-16

Assembly 2-88

Assembly component layout 5-109

Assembly Hole feature 6-71

Assembly Modeling Approach 2-6

Assembly Techniques 5-78, 5-109

Assembly Template 5-79, 6-12

Assembly toolbar 2-10

Associative Part, Assembly and Drawing 3-77

Auto Balloon 3-70

Autocad files 6-117

Auto-start projected view 3-26

Auto-transitioning 4-79

Auxiliary View 3-31, 3-32, 3-79

Axle 1-107

B

Back Iso View 1-71

Balloon 3-70

B-ANSI-MM Drawing Template 3-22

Base feature 1-99

Base Flange 6-85

BATTERY Extrude Base 4-16

BATTERY Extruded Boss 4-24

BATTERY Extruded Cut 4-22

BATTERY Fillet 4-21, 4-23

Battery Loft Plane 4-48

BATTERY Overview 4-12

BATTERYANDPLATE assembly 5-88

BATTERYPLATE Overview 4-314-31

BATTERYPLATE Extruded Boss 4-34

BATTERYPLATE Fillets 4-41

Bend Allowance 6-98

Bend outside 6-38

Bends 6-36

Bill of Materials 3-67, 3-71, 3-79

Bottom up 2-6, 2-88

BOX assembly overview 6-8

BRACKET 6-84

Break Corner 6-88

BULB Circular Pattern 4-72

BULB Dome 4-72

BULB Overview 4-64

BULB Revolve Base 4-65

BULB Revolve Boss 4-68

BULB Revolved Cut Thin 4-69

C

CABINET 6-39

CAM Works 2-103

CAPANDLENS assembly 5-91

Center marks 3-48, 3-81

Centerline 1-83, 4-18. 4-48

Chamfer 1-66, 1-101, 2-39

Circle 1-51, 4-24
Circle Split Line 3-70
CircuitWorks 6-98
Circular Pattern 4-72, 4-75, 4-79, 5-30
Clearance Fit 2-44
Closed contour 6-25
Coincident 1-72
Coincident Mate Type Considerations 2-16
Coincident/Concentric Mate 2-41
Collapse 1-45, 2-49
Collision Detection 2-27
Color and Optics 1-79
Command Manager 1-15, 1-17, 2-10
Company Logo 3-19
Company Name Property 3-16
Component 5-109
Component Pattern 2-57
Component Pattern, Feature Driven 6-70
Component Properties 3-29
Concentric 2-16
Configuration Manager 3-72
Configurations for Flat State 6-61
Configurations for Formed State 6-61
Control Area 1-15, 3-8, 6-16
Convert Entities 1-66, 1-67, 4-53, 5-28, 6-25
Copy a Component 2-33
Copy Sketch Geometry 1-51, 4-25
Copy/Paste Feature 5-58
Copy/Paste features 1-71, 1-100
Copy/Paste picture 3-20
Co radial 1-77
COSMOSXpress 2-74 – 2-87, 2-98, 2-104, 2-112, 4-88
Create dimensions 3-52
Create/Edit Material 1-95
Creating Keyboard Short Cut 4-76
Crop View 3-43, 3-79
Curve Driven Pattern 6-60
CUSTOM B Sheet Format 3-21
Custom Properties 3-62
CUSTOMER Assembly 2-5, 2-67
Customize Command Manager 2-10
Customizing Toolbars 4-76

D

Dangle 1-72, 1-77
Datum Feature 3-91
Datum Planes 1-32
Delete and Edit features 4-33
Derived Component Pattern 6-99
Description Property 1-28, 1-29
Design Intent 4-78
Design Issues 5-104
Design Table 6-81, 6-98
DE-STA-CO Industry Exercise 6-121
Detail Drawing 3-37
Detail View 3-31, 3-33, 3-79
Diameter dimension 1-53
Die Cutout Palette feature 6-51
Dimension 1-40, 1-100
Dimension Holes 3-46
Dimension layer 3-39
Dimension Property box_height 6-20
Dimension Property box_width 6-20
Dimensioning Standard 1-23
Display modes 1-46, 3-36
Display with Parenthesis 3-51
Display/Delete Relations 1-77
Distance Mate 2-22
Document Properties 1-22, 3-9, 3-60
Dome 4-72, 4-79
Draft Angle 4-27, 4-78
Drawing file name 3-80
Drawing Layers 3-80
Drawing Template 3-6, 3-80
Drawing toolbars 3-8
Drawn By Property 3-62
D-Size Battery Part 4-92

E

Edge Flange 6-44, 6-45, 6-87
Edge Properties 3-29
Edit Component 6-24, 6-85
Edit features 1-73 – 1-78, 4-33, 4-79
Edit Sheet 3-14, 3-21, 3-80
Edit Sheet Format 3-14, 3-15, 3-80
Edit Sketch 4-79
Editing Component 2-88
eDrawing 5-107, 5-109, 3-97

Emerson-EPT 2-108
 Emhart Industry Example 3-92
 Enerpac Collaborative Exercise 4-96
 Equal Relation 1-52, 4-19
 Equations 6-18, 6-76, 6-98
 Exploded View 2-47, 3-67
 Explorer 1-12
 Export files 5-106
 Extruded Base 1-27, 1-63, 1-85, 1-101, 4-16, 5-24
 Extruded Boss/Base 1-42, 4-20, 4-24, 4-34, 4-35, 4-60, 4-79, 6-98
 Extruded Cut 1-101, 2-40, 5-26
 Extruded Cut 1-27, 1-54, 1-64, 1-86, 4-79
 Extruded Cut Thin 5-32, 5-110

F

Face 1-50
 Fasteners 1-48
 FEA Equation 2-75
 Feature Manager Syntax 2-14
 Feature Palette 2-29
 Feature Toolbar 1-15, 1-16, 1-17, 4-15
 FeatureManager 5-83, 6-73
 Features 1-42, 1-99
 Feedback in drawing 3-28
 File Folder 1-13
 File Locations 1-20
 File Management 1-6, 1-12
 File Name Property 3-27, 3-28
 Fillet 1-27, 1-56, 1-101, 4-21, 4-23, 4-41, 4-79
 Finish Property 3-65
 First Angle Projection 1-34
 Fixed at Origin 2-9
 Flange 6-98
 FLANGE BOLT 2-29
 FLASHLIGHT assembly 5-76
 Flashlight assembly 5-97
 Flat Pattern 6-98
 Flat Plate 4-82
 Flat state 6-36, 6-61
 Flatbar 1-105, 1-106
 Flattened 6-44, 6-99
 Flip arrows 3-42
 FlyWheel assembly 4-92
 Fold 6-94
 Fold/Unfold 6-98

Folders FeatureManager 2-59
 Font size 3-11
 Formed state 6-36, 6-61
 Front View 1-16, 3-26
 Full Round Fillet 4-42
 Functional/Geometric Rqmts. 1-26, 1-27

G

Gains Pressure slider 5-20
 Gap in extension line 3-40, 3-41
 Gap Link Valve 6-19
 Gears Educational Systems I-20, 1-105
 General Notes 3-56, 3-81
 General Options 1-21
 Geometric Relations 1-100, 4-40, 4-78
 Geometric Tolerancing 3-91
 Geometry Pattern 1-88, 5-35
 GlobalSpec 4-95
 Guide Curve 5-11, 5-108
 GUIDE Drawing 3-24
 GUIDE Part 1-81 – 1-95
 GUIDE Part Overview 1-81
 GUIDE ROD Assembly 2-7
 GUIDE-ROD Project Overview 2-5

H

Handle 5-61
 Helix/Spiral 5-38, 5-110
 Help 1-18, 1-19
 Hem 6-45, 6-98
 Hex Adapter 5-120
 Hidden Lines Removed 1-46
 Hidden Lines Visible 1-46
 Hide Component 2-40, 5-104
 Hole 6-48
 Hole Callout 3-46, 3-81
 Hole Centerlines 3-81
 Hole Symbols 3-47
 Hole Wizard 1-27, 1-101
 Hole Wizard Counterbore 4-53
 Hole Wizard Countersink 1-58
 Hole Wizard Hole 6-49, 6-72
 Hole Wizard Tapped Hole 1-90
 Hole/Shaft Designation 2-45
 Holes in-context 6-85
 Hook 5-112
 Horizontal Dimension 1-40

Horizontal Relation 1-52
 HOUSING 5-45
 HOUSING Draft 5-54
 HOUSING Extrude Base 5-46
 HOUSING Extruded Boss 5-50
 HOUSING Handle 5-61
 HOUSING Loft 5-47
 HOUSING Rib 5-56, 5-71
 HOUSING Shell 5-52
 HOUSING Sweep 5-56
 HOUSING Thread 5-56

I

IGES 6-68
 IM15-Mount Part 4-83
 Inch Units 4-14
 In-Context features 6-10
 Injection molded process, 4-30, 5-109
 InPlace Mates 6-10
 Insert Bends 6-44
 Insert Component 2-9, 2-12, 6-21,6-29, 6-84
 Insert Component, Existing Part/Assembly 2-12
 Insert Model Items 3-39
 Insert Sheet Metal Bends 6-98
 Interference 5-104
 Interference Fit 2-44
 Intersection 4-59
 ISO 1-23
 Isometric view 3-27

J & K

Jog 6-94, 6-98
 Keyboard Short Cuts 1-10
 K-factor 6-38

L

Large Assembly Mode 6-34
 Layers 3-12
 Layout sketch 6-14, 6-98
 Leader lines 3-81
 LENS Extruded Boss 4-60
 LENS HoleWizard 4-53
 LENS Overview 4-46
 LENS Revolve 4-46
 LENS Revolve Boss Thin 4-57
 LENS Shell feature 4-52
 LENSANDBULB assembly 5-81
 Mirror feature 1-88, 1-101, 5-74

LENSCAP Circular Pattern 5-30
 LENSCAP Extruded Base 5-24
 LENSCAP Extruded Cut 5-26
 LENSCAP Overview 5-23
 LENSCAP Revolved Cut Thin 5-27
 LENSCAP Shell 5-27
 LENSCAP Sweep 5-36
 Limit 2-45
 Line 1-50, 1-83, 4-36
 Linear Motion and Rotational Motion 2-7
 Linear Pattern 1-92, 1-101, 5-69, 6-48
 Linear Sketch Step and Repeat 6-59
 Link to Property 3-16, 3-63
 Link Values 6-18, 6-98
 Linkage Assembly 1-105, 2-93
 Link-and-Hook 5-124
 Loft 5-13, 5-50, 5-110
 Loft 5-50
 Louver Forming tool 6-54

M

Machine Screw 4-86
 Machined Parts 1-30
 Make Buy Decision 2-61
 Manufacturing Considerations 1-96, 6-55
 Mate 3MMCAPSCREW 2-57
 Mate 4MMCAPSCREW 2-40 – 2-42
 Mate Error 2-24, 6-75
 Mate FH-M5-30
 Mate FLANGE BOLT 2-32 – 2-33
 Mate MGPM2139 assembly 2-69
 Mate PLATE 2-20
 Mate Pop-up toolbar 2-17
 Mate ROD Component 2-17
 Mate Types 2-15
 Material inside 6-38
 Material outside 6-38
 Material Property 3-64
 Materials Editor 1-93
 Mates 2-88
 Max arc condition 4-38
 Maximize 1-16
 Measure 4-28
 MicroGroup Collaborative Exercise 6-119
 Midpoint 4-18
 Min/Max Arc Condition 3-50
 Minus Sign Collapse 1-45
 Menus 1-100

Mirror Components 6-92, 6-99
 Mirror Entities 1-83, 1-100, 4-36, 4-78. 5-48
 Miter Flange 6-88
 Model Items by feature 3-54
 Model View 3-26
 Modify Dialog box 1-41, 1-42
 Modify Dimension 1-43
 Modify Dimension Scheme 3-50
 Modify Sketch 6-52
 MOTHERBOARD 6-21
 Move Dimension 3-40, 3-45
 Move View 3-30
 Move/Rotate Component 2-18
 Multi Radius Fillet 4-43
 Multi-body 4-35

N

Named Views 1-70
 Neutral Plane 5-55
 New Assembly 2-9
 New Drawing 3-7
 New Folder 1-12
 New Part 1-14, 4-14
 New Part Advanced 1-14
 New Part Novice 1-14
 New Step 2-47
 Next Assembly 3-66
 Normal To 1-65
 Note to Instructors I-20
 Notes 3-17, 3-79
 Number Property 3-62

O

Obround Relief 6-39
 Offset Bi-directional 4-61
 Offset Entities 4-22, 4-34
 Online Help 1-18
 Online Tutorial 1-19
 O-RING Overview 5-7
 O-RING Sweep 5-8
 Orthographic Projection 1-32 – 1-36

P

Pan 1-47
 Parallel 2-16
 Parametric note 3-57
 Part Color 1-79
 Part Templates 1-22 – 1-25, 4-15, 6-12
 Part file name 3-80
 Part Number 3-60
 Partial Auxiliary View 3-43
 PART-IN-ANSI Template 4-14
 PART-MM-ANSI Template 1-22 – 1-25
 PART-MM-ISO 4-15
 Pattern 5-110
 PEM Inserts 6-66
 Performance in drawing 3-36
 Perpendicular 4-74
 PhotoWorks 1-111
 Physical Simulation 2-96
 Pierce 5-9, 5-40
 Plane On Surface 5-30
 Plane Offset 5-48
 Plane Parallel at Point 5-71, 6-91
 Planes 1-100
 PLATE Extruded Cut 1-49
 PLATE Part 1-26 – 1-61
 PLATE Fillet feature 1-56, 1-57
 PLATE Hole Wizard 1-58
 PLATE Overview 1-26
 PLATE Extruded Base feature 1-36
 Pneumatic On-Off-Purge Valve 2-100
 Pneumatic Test Module 6-108
 Point 1-50, 5-17
 POWERSUPPLY 6-21
 Product Data Management (PDM) 6-120
 Properties 1-78, 3-61, 3-81
 Push Pin 1-71

Q&R

Quick Tops 1-19
 Rebuild 1-100, 2-9
 Rebuild Error 1-75
 Rectangle 1-37, 4-17
 Rectangular Relief 6-39
 Reference Planes 1-32
 Reid Tool Supply Co 1-103

- Relief 6-39
- Reload 6-99
- Rename 1-45
- Reorder Bill of Materials 3-75
- Replace component 6-75, 6-99
- Reservoir Assembly 4-87
- Reverse Direction 1-42
- Revision Property 3-62
- Revision table 3-58 – 3-60, 3-79
- Revolve Base feature 2-36 –2-39, 4-46, 4-65
- Revolved Boss 4-51, 4-68, 4-79
- Revolved Boss Thin 4-57
- Revolved Cut 4-70, 4-79
- Revolved Cut Thin 4-69, 5-27, 5-110
- Rib – end contours 5-71
- Rib 5-56, 5-71, 5-110
- Right view 3-26
- Rip feature 6-42, 6-98
- ROD 1-61 – 1-80
- ROD Part Overview 1-61
- Rollback 1-73 – 1-78
- Rotate 1-47
- Rotate Component Delta XYZ 2-68
- S**
- Save 1-28, 2-11
- Save As 2-90
- Save as Copy 2-55
- Save As Copy, References 2-71
- Save Drawing Template 3-22
- Save Part Templates 1-24
- Save Sheet Format 3-21
- Schematic diagram 6-114
- Section View 2-51, 3-31, 3-32, 3-79. 5-96
- Section View Short Cut 4-76
- Select 1-38
- Select Filter 2-21, 2-23
- Servo Bracket 2-101
- Shaded 1-46
- Shaded with Edges 1-46
- Shaft Collar 1-108
- Shape 5-19, 5-110
- Shape icon 4-76
- Sheet Format 3-6, 3-80
- Sheet Format dialog box 3-7
- Sheet metal bends 6-42
- Sheet metal drawing 6-63
- Sheet Metal Overview 6-35
- Sheet Properties 3-9, 3-29
- Shell 4-52, 5-27, 6-41, 6-98
- Short Cut Keys 1-10
- Shortcut menus 1-38
- Show Component 5-105
- Show Me 1-18, 1-19
- Silhouette Edge 4-58
- Simpson Strong Tie 6-101, 6-102
- Sketch 1-37, 1-100
- Sketch Driven Pattern 6-60
- Sketch Polygon(hexagon) 2-40
- Sketch toolbar 4-15
- Sketched Bend lines 6-36
- Sketched Features 1-99
- Slot Sketch 1-86
- Smart Dimension 1-40
- Smart Fastener 2-62
- Smart Mates 2-31, 2-89
- SMC Components 2-63
- SMC Corporation of America 1-107
- Spin Box Increments 4-14
- Spline 4-68, 4-79
- Split Bar 2-49
- Standard View 1-16
- Start SolidWorks 1-14
- Status of Sketch 1-100
- Step Editing Tools 2-49
- Stereo Lithography (STL) 5-109
- STL Files 5-106
- Stress and Strain 2-76
- Summary Information 3-16, 3-61
- Suppress feature 5-35, 5-110, 6-99
- Suppressed Components 2-60
- Surface Plane 5-31
- SW/Animator 2-104
- Sweep 5-8, 5-16, 5-38, 5-56, 5-61, 5-108, 5-110
- Sweep, Complex 5-11
- SWITCH Overview 5-13
- SWITCH Shape 5-19
- Symbols 3-18
- System feedback 1-100
- System Options 1-20, 1-21
- System Options File Locations 3-22

T

Table Driven Pattern 6-60
Tangent Arc 1-86, 4-37
Tear Relief 6-39
Temporary Axis 4-51
Temporary Axis in drawing 3-44
Third Angle 3-9
Third Angle Projection 1-34
Thread 5-11, 5-36
Thread Copy/Paste 5-58
Thread Plane 5-37
Thread Profile 5-39
Through All End Condition 1-54
Thumbnails 2-8
Tip of the Day 1-20
Title Block 3-13, 3-80
Tolerance & Fit 2-43
Tolerance block 3-17, 3-18
Tolerance/Precision 1-98
Toolbars 1-16, 1-17, 1-100
Toolbox 2-61
Tools, Measure 4-28
Tools, Options 1-20
Top down 2-6, 2-88, 6-6, 6-98
Top view 3-26
Transition Fit 2-44
Transparent 4-63
Triangle Support assembly 6-103
Trim Entities 1-67 – 1-68, 4-78
True developed length 6-37

U & V

Unfold 6-93
Units 1-24, 4-14
Unsuppress 2-71
Up to Surface 4-41
Used On 3-66
User Specified Name 3-72
Vertex 1-50
Vertical Dimension 1-40
View Appearance 3-80
View modes 1-47
View Orientation 1-49, 1-70
View Properties 3-29

W, X, Y, Z

Weight 5-113
What is SolidWorks? 1-13
Wheel part 5-121
Wheel-and-Axle assembly 5-116, 5-123,
6-109
Windows Terminology 1-7 – 1-9
Wireframe 1-46
Zoom In/Out 1-47
Zoom to Area 1-47
Zoom to Fit 1-47
Zoom to Selection 1-47